CERTIFICATE OF COMPLIANCE

Certificate Number	20120914-E125551
Report Reference	E108847-20040325
Issue Date	2012-SEPTEMBER-14

Issued to: SIMU U S INC
14, 6100 BROKEN SOUND PKY NW
BOCA RATON FL 33487

This is to certify that representative samples of DOOR, DRAPERY, GATE, LOUVER, AND WINDOW OPERATORS AND SYSTEMS
See Addendum Page

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 325, Door, Drapery, Gate, Louver, and Window Operators and Systems
C22.2 No. 247, Operators and Systems of Doors, Gates, Draperies and Louvres

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Listing Mark for the US and Canada should be considered as being covered by UL's Listing and Follow-Up Service meeting the appropriate requirements for US and Canada.
The UL Listing Mark for the US and Canada generally includes: the UL in a circle symbol with “C” and “US” identifiers: c UL us the word “LISTED”; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

Look for the UL Listing Mark on the product.

William R. Carney

William R. Carney, Director, North American Certification Programs

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus

CERTIFICATE OF COMPLIANCE

Certificate Number	20120914-E125551
Report Reference	E108847-20040325
Issue Date	2012-SEPTEMBER-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

PRODUCT COVERED:

USL, CNL: Tubular Motor Operators for Exterior Awnings and Shutters (Window Coverage products: awnings, blinds, rolling shutters), Models DMI505.35HU, DMI510.12HU, DMI510.35HU, DMI515.18HU, DMI520.12HU, DMI525.18HU, DMI530.12HU, DMI535.18HU, DMI540.12HU, DMI550.12HU, DMI625.54HU, DMI660.14HU, DMI680.14HU, DMI6100.14HU, HzDMI505.35HU, HzDMI510.12HU, HzDMI510.35HU, HzDMI515.18HU, HzDMI520.12HU, HzDMI525.18HU, HzDMI530.12HU, HzDMI535.18HU, HzDMI540.12HU, HzDMI550.12HU, HzDMI625.54HU, HzDMI660.14HU, HzDMI680.14HU, HzDMI6100.14HU

William R. Carney

William R. Carney, Director, North American Certification Programs

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus